

Yealink SIP Phone Release Notes

1. Introduction

Firmware Versions:

T19P E2: 53.84.0.160

T21 E2: 52.84.0.160

T23G: 44.84.0.160

T27G: 69.86.0.160

T27P: 45.83.0.160

T29G: 46.83.0.160

T40P: 54.84.0.160

T41P: 36.83.0.160

T41S: 66.86.0.160

T42S: 66.86.0.160

T46S: 66.86.0.160

T48S: 66.86.0.160

T40G: 76.84.0.160

T42G: 29.83.0.160

T46G: 28.83.0.160

T48G: 35.83.0.160

T52S: 70.84.0.160

T54S: 70.84.0.160

T58V: 58.86.0.160

CP920: 78.86.0.160

CP960: 73.86.0.160

2. New Features

None

3. Optimizations

None

4. Bug Fixes

1. Fixed phone bugs reported by the market.

Note: To ensure the stability of the upgraded version, T58V/CP960 cannot be downgraded to previously released versions after the upgrade.